



LiPo 3S
BATTERY








WARNING
- +
• +5V

WARNING
- + V
• +12V

WARNING
- +



(Official website): <http://www.openpilot.org/>
(Hardware) <http://wiki.openpilot.org/display/Doc/CopterControl+Hardware+Manual>
(Instructions) <http://wiki.openpilot.org/pages/viewpage.action?pageId=20250682>
wiki:
<http://wiki.openpilot.org/display/Doc/CopterControl+Hardware+Manual>





Arming Settings

Arm airframe using throttle off and:

Arming timeout: seconds (0 to disable).

Airframe disarm is done by throttle off and opposite of above combination.

Roll

Stabilized 0

Stabilized 1

Stabilized 2